

PPE Checklist

Contact and Droplet Precautions

Steps for putting on PPE			Steps for taking off PPE		
1		Clean hands	1		Gloves
2		Gown	2		Clean hands
3	 	Mask with visor or mask and eye protection	3		Gown
4		Gloves	4		Clean hands
			5	 	Mask with visor or mask and eye protection
			6	 	Hand sanitizer or soap and water